

SAFETY DATA SHEET R 34 CE Part B

1. IDENTIFICATION OF THE SUBSTANCE/PREPARATION AND OF THE COMPANY/UNDERTAKING

PRODUCT NAME R 34 CE Part B

SUPPLIER ARDEX ENDURA (INDIA) PRIVATE LIMITED

Corporate Office & Regd. Office:

Unit No. 406 & 407, "Brigade Rubix", No. 20, Yeshwanthapur Hobli,

HMT Campus, Bangalore - 560022. Karnataka, INDIA.

CIN No: U24233KA1997PTC022383

Tel: +91 80 66746500 Fax: +91 80 66746540

Email: customercare@ardexendura.com Visit us: www.ardexendura.com

2. HAZARDS IDENTIFICATION

HUMAN HEALTH HAZARDS

May be moderately toxic if swallowed. Slightly toxic and may be harmful if absorbsd through the skin. May be corrosive to the eyes. May be corrosive to the skin. May be corrosive to respiratory tract. May be corrosive to mouth, throat, and stomach. May cause skin sensitization.

SAFETY HAZARDS

Corrosive material will not burn unless preheated.

3. COMPOSITION/INFORMATION ON INGREDIENTS

Cycloaliphatic amine and other proprietry components.

4. FIRST-AID MEASURES

INHALATION

Do not attempt to rescue the victim uniess proper respiratory protection is worn. Remove victim to fresh air and provide oxygen if breathing is difficult. Get medical attention.

INGESTION

Do not induce vomiting. Have victim rinse out mouth with water, then drunk sips of water to remove taste from mouth. Do not give liquids to a drowsy, convulsing or unconscious person. If vomiting occurs spontaneously, keep head below hips to prevent aspiration. Get medical attention.

SKIN CONTACT

Immediately remove contaminated clothing. Flush with large amounts of water for at least 15 minutes. Flush exposed skin with water and follow by washing with soap if available. Transport to nearest medical facility for additional treatment.

EYE CONTACT

Immediately flush eyes with plenty of water for 15 minutes while holding eyelids open. Transport to nearest medical factility for additional treatment.

5. FIRE-FIGHTING MEASURES

EXTINGUISHING MEDIA

Use water fog "alcohol foam", dry chemical or carbondioxide. Water fog may cause forthing which can be violent, especially if sprayed into containers of hot or burning liquid.

SPECIFIC HAZARDS DURING FIRE FIGHTING:

Materials will not burn unless preheated. Nirogen oxides and other potentially hazardous nitrogen-containing compounds may be released upon combustion. Evacuate the area of all non-essential personnel. Container areas exposed to direct flame contact should be cooled with large quantities of water as needed to prevent weakening of container structure. Cool fire exposed containers with water.

SPECIAL PROTECTIVE EQUIPMENT FOR FIRE- FIGHTERS

Do not enter confined fire space without full bunker gear (helmet with face shield, bunker coats, gloves, and rubber boots) including a self-contained breathing apparatus.

R 34 CE Part B

6. ACCIDENTAL RELEASE MEASURES

PERSONAL PRECAUTIONS

Remove ignition sources. Prevent ail bodily contact with spilled materials. Use cautious judgments whe cleaning up large spills. Shut off leaks, if possible without personal risk.

ENVIRONMENTAL PRECAUTIONS

Contains run-off and dispose of properly. Neutralize contaminated areas as appropriate for acid or base spill. Prevent from entering into drains, ditches or rivers.

RESPIRATORY PROTECTION

Donot breath vapour or mists. Use an approved respirator as required to prevent overexposure. The types of respirator(s) to be considered includes: Air-Purifying Respirator for Organic Vapour. Full-Face Supplied-Air Respirator. Self-Contained Breathing Apparatus (SCBA) for use in environments with unknown concentration or emergency situations.

7. HANDLING AND STORAGE

ADVICE ON SAFE HANDLING

Do not get in eyes, or skin or on clothing. Do not taste pr swallow. Do not breath material. Use only with adequate ventilation. Aviod contact with skin, eyes, and clothing. Wash thoroughly after handling. Heating this curing agent above 140°C in the precence of air may cause slow oxidative decomposition: above 260°C. polymerization may occur. Some epoxy resins can produce exothermic reaction which in large masses can cause runaway polymerization and charring of the reactants. Fumes and vapors from these thermal and chemical decomposition vary widely in composition and toxicity. May be corrosive to the eyes. May be corrosive to skin. Corrosive to the diggestive tract. Toxic and harmful if inhaled. Slightly toxic and may be harmful if absorbed through the skin. May be moderately toxic if swallowed. May be corrosive to the respiratory tract. May cause skin sensitization. Wash with soap and water before eating, drinking, smoking, applying cosmetics, or using toilet facilities. Launder contaminated clothing before reuse. Contaminated leather articles, including shoes, cannot be decontaminated and should be destroyed to prevent reuse. Do not pressurize drum container to empty them. Do not breathe fumes. Use atmosphere supplying respirator or an air-purifing respirator for organic vapour. Containers, even those that have been emptied, can contain hazardous product residues.

REQUIREMENTS FOR STORAGE AREAS AND CONTAINERS

Store in a cool, dry place with adequate ventilation. Keep away from open flames and hhigh temperature. Keep containers closed when not in use.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

PROTECTIVE MEASURES

Wear appropriate respirator and full-body protective clothing.

ENGINEERING MEASURES

Adequate ventilation to control airborne concentration. Eye wash fountain and safety showers should be available for emergency use.

EYE PROTECTIONS

Do not get in eyes. Wear chemical goggles.

SKIN AND BODY PROTECTIONS

Do not get on skin, on clothing. Wear chemical resistant protective clothing such as gloves, outer clothing or apron, overshoes and a face-shield suitable to potential exposure.

RESPIRATORY PROTECTIONS

Do not breath vapors or mists. Use an approved respirator as required to prevent overexposure. Air purifying respirator for Organic Vapors. Full-face Supplied-Air Respirator. Self- Contained Breathing Apparatus (SCBA) for use in environments with unknown concentration or emergency situations.

9. PHYSICAL AND CHEMICAL PROPERTIES

FORM Liquid

COLOR Light yellow colour

ODOR Amine SOLUBILITY IN WATER N/A

10. STABILITY AND REACTIVITY

CONDITION TO AVOID

Aviod high temperatures.

MATERIALS TO AVOID

Can react vigorously with strong oxidizing agents, strong Lewis or mineral acid, and strong mineral and Organic bases. Reaction with some resins may produce considerable heat and possible violent decomposition.

REVISION DATE: 01/04/2014

R 34 CE Part B

HAZARDOUS REACTION

Stable under normal use condition. Hazardous polymerization will not occur.

11. TOXICOLOGICAL INFORMATION

POTENTIAL HEALTH EFFECTS

INHALATION

May be corrosive to the nose, throat and respiratory tract.

SKIN

May be corrosive (causing chemical bruns). May be harmful if absorbed through the skin. May cause skin sensitization.

FYES

May be corrosive to the eyes and vapors may be irritating.

INGESTION

May cause damage to mouth, throat and stomach.

12. ECOLOGICAL INFORMATION

There is no data available for this product.

13. DISPOSAL CONSIDERATIONS

This materials may be disposed of as per local regulation.

14. TRANSPORT INFORMATION

No Specific transportation is required and not applicable.

15. REGULATORY INFORMATION

The regulatory information is not intended to be comprehensive. Other regulation may apply to this materials.

16. OTHER INFORMATION

TRAINING ADVICE : The details of this data sheet must be passed on to all personnel handling the product.

DISCLAIMER

This information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process. Such information is, to the best of the company's knowledge and belief, accurate and reliable as of the date indicated. However, no warranty guarantee or representation is made to its accuracy, reliability or completeness. It is the user's responsibility to satisfy himself as to the suitability of such information for his own particular use.